



PET MACHINE : CONNECTIQUE



BORNIER

RV	S	U	M	L	N	O	G	F	H	I	C	AE	B
14	13	12	11	10	9	8	7	6	5	4	3	2	1
+	-	+	Q	P	+	-	K	J	+	-	+	-	D

PET MACHINE : SCHEMA GENERAL



BORNIER

B	1
AE	2
C	3
I	4
H	5
F	6
G	7
O	8
N	9
L	10
M	11
U	12
S	13
RV	14

1	D
2	-
3	+
4	-
5	+
6	J
7	K
8	-
9	+
10	P
11	Q
12	+
13	-
14	+